#### MT 35/US 93 Truck Study

#### **Focus Group Meeting**



Director Jim Lynch Montana Department of Transportation

November 19, 2008 Kalispell, Montana



#### Additional Analysis

Based on comments received during and after the public meetings, MDT collected the following additional information:

- MT 35 speed zone study
- Structural analysis of the Swan River bridge at Bigfork
- Pavement structural analysis on MT 35
- Results of Motor Carrier Services expanded enforcement on MT 35
- Truck use of alternate routes (fuel consumption and travel time)
- "Off-Tracking Study" at posted speed limits

### Speed Zone Study

- ■Travel speeds were sampled directionally at nine locations on MT 35. Each sample was collected with an automated traffic counter over a 24-hour period in July 2008
- MDT also monitored speeds at Reference Markers 10, 16, 23, and 29
- Trucks included both single unit trucks and tractor-trailer combinations.

## Speed Zone Study

#### **Results:**

- Speeds were consistently between 47 mph and 57 mph with approximately 70 percent of the traffic stream traveling within this range
- Between 50 and 75 percent of drivers exceeded the current 50 mile per hour speed limit
- The most common travel speeds observed were just above the 50 mph speed limit with the highest percentage of drivers traveling between 51 mph and 54 mph
- The speed data for both single unit and tractor-trailer combination trucks mirrored the speeds of passenger cars

#### Swan River Bridge

- The Swan River Bridge at Bigfork was built in 1954 and is approximately 220 feet long
- The roadway width on the bridge is 28 feet which matches the roadway width on the approaches
- "Sufficiency Rating"
  - 48 on a 0-100 scale due to the bridge width
  - A width of 28 feet is considered fairly narrow for the traffic volumes
  - Bridge meets minimum standards to remain in place
- "Health Index"
  - 90 on a scale of 0-100
  - This rating indicates the bridge is structurally sound
  - Bridge will last a fairly long time from a component life standpoint

#### Pavement Analysis

Purpose: Estimate MT 35 pavement structural capacity and determine if the pavement is capable of supporting trucks


- Roadway between Polson and Bigfork was constructed 1936-1948
- •Pavement thickness ranges from 5.4 inches at RM 12 to 14.4 inches at RM 22
- Pavement conditions include alligator cracking and aging
- Frequent maintenance work is required
- •Roadway is generally smooth between Reference Markers 4 & 26
- Roadway is roughest between RM 26 and 32

Reference	e Markers	IRI*	
Start	End		
3.6	7.1	84	
7.1	10.2	79	
10.3	18	86	
18	26.3	90	
26.3	32.6	147	

<sup>\*</sup>International Roughness Index

#### Pavement Analysis


#### International Roughness Index (IRI) on MT 35 in 1998, 2003, and 2008



- Between 1998 and 2008, the pavement from RM 4 to RM 18 deteriorated at a relatively slow rate
- The pavement from RM 18 to RM 26 deteriorated rapidly between 1998 and 2003, and improved in 2008 due to an overlay in 2005
- The pavement between RM 26 and RM 32 is also deteriorating rapidly and needs treatment

Conclusion: MT 35 is structurally capable of carrying heavy truck traffic. However, frequent short-term maintenance fixes are necessary pending major rehabilitation or construction

#### Pavement Analysis





#### Expanded MCS Enforcement


- Intent was to show increased enforcement presence and to check compliance with MCS laws
  - Effort lasted 25 days for a total of 720 hours with MCS officers using random patrol, video, and portable scales
  - Officers observed that truck traffic tended to shift from MT
    35 to US 93 when they were actively working on MT 35
  - A few citations were issued at the beginning of the effort but none after that
  - Truck drivers obeyed the speed limit when patrols were active


#### Alternate Truck Routes

Termini		Miles	Fuel	Time	Route
Start	End	Ivilles	ruei	Time	Route
US 93 West Shore Routes					
A. Polson*	Col. Falls/Plum Creek	71	12.6 gal	1 hour, 49 min	Polson–US 93-Reserve-US 2–Plum Creek
B. Polson*	Col. Falls/Plum Creek	76	14.2 gal	1 hour, 43 min	Polson-US 93-MT 82-MT 35-S 206-US 2-Plum Creek
MT 35 East Shore Routes					
C. Polson*	Col. Falls/Plum Creek	58	11.7 gal	1 hour, 20 min	Polson-MT 35-S 206-US 2- Plum Creek
D. Polson*	Col. Falls/Plum Creek	66	15.7 gal**	1 hour, 40 min	Polson-MT 35-MT 82-US 93-Reserve-US 2-Plum Creek









Intent of study was to observe truck drivers' ability to stay within lane boundaries while driving at the posted speed limits

#### **MT 35**

- MDT conducted the study in cooperation with the industry trucks
- Two fuel trucks (truck trailer and tractor-trailer plus trailer); and three trucks (log truck, chip truck, and belly dump construction truck) all consisting of a tractor trailer plus a trailer
- Drivers participating in the study were aware they were being followed and videotaped
- Drivers negotiated the roadway well, keeping the trucks and trailers in the driving lanes and observing the speed limit.
- There were few cases observed when trucks crossed into the centerline area.

#### MT 35 continued

- MDT also observed drivers traveling on MT 35 who did not know they were being videotaped
- Trucks included a food service tractor trailer, a fuel truck with no trailer, a fuel truck with pup, and a truck/lowboy trailer with no load
- Again, there were a minimal number of encroachments and only over the centerline
- MDT also monitored several other vehicles including a passenger car, a power company truck pulling a trailer, a Suburban, and a pickup truck with horse trailer
- Most stayed in their lane with the exception of the pickup truck with horse trailer

#### **US 93**

- On October 28, MDT staff monitored eight randomly selected vehicles traveling both north and south between Somers and Lakeside whose drivers had no prior knowledge they were being videotaped
- Vehicles included an SUV, a truck, a passenger car, a box store tractor-trailer, a utility truck, a truck with a flatbed trailer, a log truck, and a full-size pickup
- There were few encroachments into the centerline area

The following video shows MCS officers following one of the five participating trucks (tractor-trailer plus trailer fuel truck from City Service)



# Questions?

